



A.5 EMISSION LIMITATIONS MEASUREMENT

Test Date	2017/11/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	I
		Frequency	TX 5180MHz
Cable Loss	3dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0 for 802.11a, 3for 802.11n-HT20/40 and 802.11ac-VHT80		



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.


No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City244, Taiwan

Tel: +886 2 26099301


Fax: +886 2 26099303

Test Date	2017/11/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	I
Cable Loss	3dB	Frequency	TX 5200MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0 for 802.11a, 3for 802.11n-HT20/40 and 802.11ac-VHT80		



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.


No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City 244, Taiwan

Tel: +886 2 26099301

Fax: +886 2 26099303

Test Date	2017/11/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	I
Cable Loss	3dB	Frequency	TX 5240MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0 for 802.11a, 3 for 802.11n-HT20/40 and 802.11ac-VHT80		




Audix Technology Corp.

No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City244, Taiwan

Tel: +886 2 26099301

Fax: +886 2 26099303



Audix Technology Corp.


No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City244, Taiwan

Tel: +886 2 26099301


Fax: +886 2 26099303

Test Date	2017/11/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2A
Cable Loss	3dB	Frequency	TX 5260MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0 for 802.11a, 3for 802.11n-HT20/40 and 802.11ac-VHT80		



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.


No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City244, Taiwan

Tel: +886 2 26099301


Fax: +886 2 26099303

Test Date	2017/11/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2A
Cable Loss	3dB	Frequency	TX 5300MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0 for 802.11a, 3for 802.11n-HT20/40 and 802.11ac-VHT80		



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.

No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City244, Taiwan

Tel: +886 2 26099301


Fax: +886 2 26099303

Test Date	2017/11/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2A
Cable Loss	3dB	Frequency	TX 5320MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	0 for 802.11a, 3for 802.11n-HT20/40 and 802.11ac-VHT80		




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Test Date	2017/11/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2C
Cable Loss	3dB	Frequency	TX 5500MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	0 for 802.11a, 3for 802.11n-HT20/40 and 802.11ac-VHT80		



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.

No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City244, Taiwan

Tel: +886 2 26099301


Fax: +886 2 26099303

Test Date	2017/11/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2C
Cable Loss	3dB	Frequency	TX 5580MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	0 for 802.11a, 3for 802.11n-HT20/40 and 802.11ac-VHT80		



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.


No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City244, Taiwan

Tel: +886 2 26099301


Fax: +886 2 26099303

Test Date	2017/11/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2C
Cable Loss	3dB	Frequency	TX 5700MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	0 for 802.11a, 3for 802.11n-HT20/40 and 802.11ac-VHT80		



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.






No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City244, Taiwan

Tel: +886 2 26099301

Fax: +886 2 26099303

Test Date	2017/11/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2C
Cable Loss	3dB	Frequency	TX 5720MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	0 for 802.11a, 3for 802.11n-HT20/40 and 802.11ac-VHT80		





Audix Technology Corp.






No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City 244, Taiwan

Tel: +886 2 26099301

Fax: +886 2 26099303

Test Date	2017/11/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	III
Cable Loss	3dB	Frequency	TX 5745MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0 for 802.11a, 3 for 802.11n-HT20/40 and 802.11ac-VHT80		





Audix Technology Corp.


No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City 244, Taiwan

Tel: +886 2 26099301


Fax: +886 2 26099303

Test Date	2017/11/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	III
Cable Loss	3dB	Frequency	TX 5785MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0 for 802.11a, 3for 802.11n-HT20/40 and 802.11ac-VHT80		



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.

No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City 244, Taiwan

Tel: +886 2 26099301

Fax: +886 2 26099303

Test Date	2017/11/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	III
Cable Loss	3dB	Frequency	TX 5825MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
		0 for 802.11a, 3for 802.11n-HT20/40 and 802.11ac-VHT80	

