

A.4 MAXIMUM OUTPUT POWER

Test Date	2018/10/20~11~03	Temp./Hum.	25°C/55%
Cable Loss	Band I: 2.92dB Band II-2A/2C: 3.37dB Band III: 3.91dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)

A.4.1 Average Output Power

Mode	UNII Band	Centre Frequency (MHz)	Average Output Power (dBm)		10log (1/X)	Total Average Output Power				Limit
			Chain 0	Chain 1		Chain 0		Chain 1		
		(dBm)				(W)	(dBm)	(W)		
802.11a	I	5180	18.43	17.55	0	18.43	0.070	17.55	0.057	< 250 mW (24 dBm)
		5200	21.11	20.47		21.11	0.129	20.47	0.111	
		5240	20.53	20.55		20.53	0.113	20.55	0.114	
	II-2A	5260	20.61	20.64		20.61	0.115	20.64	0.116	
		5300	20.12	20.02		20.12	0.103	20.02	0.100	
		5320	17.52	17.38		17.52	0.056	17.38	0.055	
	II-2C	5500	16.77	17.16		16.77	0.048	17.16	0.052	
		5580	21.01	21.26		21.01	0.126	21.26	0.134	
		5700	18.38	18.04		18.38	0.069	18.04	0.064	
	III	5745	21.45	21.37		21.45	0.140	21.37	0.137	< 1 W (30 dBm)
		5785	21.17	21.09		21.17	0.131	21.09	0.129	
		5825	20.12	20.58		20.12	0.103	20.58	0.114	

Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303


Mode	UNII Band	Centre Frequency (MHz)	Average Output Power(dBm)		10log (1/X)	Total Average Output Power		Limit
			Chain 0	Chain 1		(dBm)	(W)	
802.11n-HT20	I	5180	15.34	16.22	0.19	19.01	0.080	< 250 mW (24 dBm)
		5200	18.04	18.23		21.34	0.136	
		5240	17.81	18.13		21.18	0.131	
	II-2A	5260	18.21	18.37		21.50	0.141	
		5300	18.26	18.04		21.36	0.137	
		5320	15.52	15.24		18.59	0.072	
	II-2C	5500	15.78	15.73		18.96	0.079	
		5580	18.65	17.35		21.25	0.133	
		5700	17.53	17.72		20.83	0.121	
		5720	19.45	19.72		22.79	0.190	
	III	5745	20.04	20.34		23.40	0.219	< 1 W (30 dBm)
		5785	19.81	20.06		23.14	0.206	
		5825	19.97	20.73		23.57	0.228	
802.11n-HT40	I	5190	13.61	13.56	0.38	16.97	0.050	< 250 mW (24 dBm)
		5230	17.93	16.83		20.80	0.120	
	II-2A	5270	18.27	18.61		21.83	0.152	
		5310	13.74	14.65		17.61	0.058	
	II-2C	5510	12.15	12.83		15.89	0.039	
		5550	16.82	16.76		20.18	0.104	
		5670	16.95	18.26		21.04	0.127	
		5710	19.80	20.25		23.42	0.220	
	III	5755	17.41	17.53		20.86	0.122	< 1 W (30 dBm)
		5795	19.74	19.85		23.18	0.208	
802.11ac-VHT80	I	5210	8.53	9.73	0.76	12.94	0.020	< 250 mW (24 dBm)
	II-2A	5290	11.19	11.63		15.18	0.033	
	II-2C	5530	10.21	12.54		15.30	0.034	
		5610	17.45	17.24		21.11	0.129	
		5690	19.23	18.58		22.69	0.186	
	III	5775	12.66	13.81		17.04	0.051	< 1 W (30 dBm)
802.11ac-VHT160	I	5250	10.71	9.84	1.18	14.06	0.025	< 250 mW (24 dBm)
	II-2C	5570	11.0	10.86		14.70	0.030	


Note: The results have been included cable loss.

A.4.2 Measurement Plots

- Output Power








A.5 EMISSION LIMITATIONS MEASUREMENT

Test Date	2018/10/27	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	I
		Frequency	TX 5180MHz
Cable Loss	2.92dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/10/27	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	I
		Frequency	TX 5200MHz
Cable Loss	2.92dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

APPENDIX A-Page 63 of 157


Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/10/27	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	I
		Frequency	TX 5240MHz
Cable Loss	2.92dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

APPENDIX A-Page 65 of 157

Tel: +886 2 26099301
Fax: +886 2 26099303



Test Date	2018/10/29	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2A
		Frequency	TX 5260MHz
Cable Loss	3.37dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

APPENDIX A-Page 67 of 157

Tel: +886 2 26099301
Fax: +886 2 26099303



Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2A
		Frequency	TX 5300MHz
Cable Loss	3.37dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

APPENDIX A-Page 69 of 157

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.


No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City244, Taiwan

Tel: +886 2 26099301

Fax: +886 2 26099303

Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2A
		Frequency	TX 5320MHz
Cable Loss	3.37dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor10 log(n) (Note: “n” is antenna number)			0







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

APPENDIX A-Page 71 of 157

Tel: +886 2 26099301
Fax: +886 2 26099303



Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2C
		Frequency	TX 5500MHz
Cable Loss	3.37dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

APPENDIX A-Page 73 of 157

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.


No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City 244, Taiwan

Tel: +886 2 26099301

Fax: +886 2 26099303

Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2C
		Frequency	TX 5580MHz
Cable Loss	3.37dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

APPENDIX A-Page 75 of 157

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.


No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City 244, Taiwan

Tel: +886 2 26099301

Fax: +886 2 26099303

Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2C
		Frequency	TX 5700MHz
Cable Loss	3.37dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0











Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


APPENDIX A-Page 77 of 157

Tel: +886 2 26099301
Fax: +886 2 26099303




Test Date	2018/10/31	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	III
		Frequency	TX 5745MHz
Cable Loss	3.91dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0





Test Date	2018/10/31	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	III
Cable Loss	3.91dB	Frequency	TX 5785MHz
Simultaneous Factor	10 log(n) (Note: "n" is antenna number)	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
			0






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

APPENDIX A-Page 81 of 157

Tel: +886 2 26099301
Fax: +886 2 26099303



Test Date	2018/10/31	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	III
Cable Loss	3.91dB	Frequency	TX 5825MHz
Simultaneous Factor	10 log(n) (Note: "n" is antenna number)	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
			0

