Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE20	
AUX	Main
U-NII Band 1	U-NII Band 1
5180MHz	5180MHz
RU Configuration: 26/0	RU Configuration: 26/0
	
RU Configuration: 52/37	RU Configuration: 52/37
	
RU Configuration: 106/53	RU Configuration: 106/53
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE20	
AUX	Main
U-NII Band 2A	U-NII Band 2A
5320MHz	5320MHz
RU Configuration: 26/8	RU Configuration: 26/8
	
RU Configuration: 52/40	RU Configuration: 52/40
	
RU Configuration: 106/54	RU Configuration: 106/54
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ac-HE20	
AUX	Main
U-NII Band 2C	U-NII Band 2C
5500MHz	5500MHz
RU Configuration: 26/0	RU Configuration: 26/0
	
RU Configuration: 52/37	RU Configuration: 52/37
	
RU Configuration: 106/53	RU Configuration: 106/53
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ac-HE20	
AUX	Main
U-NII Band 2C	U-NII Band 2C
5700MHz	5700MHz
RU Configuration: 26/8	RU Configuration: 26/8
	
RU Configuration: 52/40	RU Configuration: 52/40
	
RU Configuration: 106/54	RU Configuration: 106/54
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ac-HE20	
AUX	Main
U-NII Band 3	U-NII Band 3
5745MHz	5745MHz
RU Configuration: 26/0	RU Configuration: 26/0
	
RU Configuration: 52/37	RU Configuration: 52/37
	
RU Configuration: 106/53	RU Configuration: 106/53
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ac-HE20	
AUX	Main
U-NII Band 3	U-NII Band 3
5825MHz	5825MHz
RU Configuration: 26/8	RU Configuration: 26/8
	
RU Configuration: 52/40	RU Configuration: 52/40
	
RU Configuration: 106/54	RU Configuration: 106/54
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE40	
AUX	Main
U-NII Band 1	U-NII Band 1
5190MHz	5190MHz
RU Configuration: 242/61	RU Configuration: 242/61
	
U-NII Band 2A	U-NII Band 2A
5310MHz	5310MHz
RU Configuration: 242/62	RU Configuration: 242/62
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE40	
AUX	Main
U-NII Band 2C	U-NII Band 2C
5510MHz	5510MHz
RU Configuration: 242/61	RU Configuration: 242/61
	
5670MHz	5670MHz
RU Configuration: 242/62	RU Configuration: 242/62
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE40	
AUX	Main
U-NII Band 3	U-NII Band 3
5755MHz	5755MHz
RU Configuration: 242/61	RU Configuration: 242/61
	
5795MHz	5795MHz
RU Configuration: 242/62	RU Configuration: 242/62
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE80	
AUX	Main
U-NII Band 1	U-NII Band 1
5210MHz	5210MHz
RU Configuration: 484/65	RU Configuration: 484/65
	
U-NII Band 2A	U-NII Band 2A
5290MHz	5290MHz
RU Configuration: 484/65	RU Configuration: 484/65
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE80	
AUX	Main
U-NII Band 2C	U-NII Band 2C
5530MHz	5530MHz
RU Configuration: 484/65	RU Configuration: 484/65
	
5610MHz	5610MHz
RU Configuration: 484/66	RU Configuration: 484/66
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE80	
AUX	Main
U-NII Band 3	U-NII Band 3
5775MHz	5775MHz
RU Configuration: 484/65	RU Configuration: 484/65
	
RU Configuration: 484/66	RU Configuration: 484/66
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE160	
AUX	Main
U-NII Band 1/2A	U-NII Band 1/2A
5250MHz	5250MHz
RU Configuration: 996/67	RU Configuration: 996/67
	
RU Configuration: 996/S67	RU Configuration: 996/S67
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE160	
AUX	Main
U-NII Band 2C	U-NII Band 2C
5570MHz	5570MHz
RU Configuration: 996/67	RU Configuration: 996/67
	
RU Configuration: 996/S67	RU Configuration: 996/S67
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan
Tel: +886 2 26099301
Fax: +886 2 26099303

A.5 FREQUENCY STABILITY

Test Date	2022/07/20	Temp./Hum.	25℃/50%
Cable Loss	---	Tested By	Kuper Hsu
Test Voltage	AC 120V 60Hz (Via AC Adapter)		

A.5.1 Frequency stability Result

Temperature (℃)	Voltage (Vac)	Centre Frequency (MHz)	Measurement Value (MHz)	Frequency Stability (ppm)
25	120	5180	5180.004	0.772
-30	102		5179.993	-1.351
	138		5180.014	2.703
-20	102		5180.025	4.826
	138		5180.008	1.544
-10	102		5180.004	0.772
	138		5180.021	4.054
0	102		5180.011	2.124
	138		5179.996	-0.772
10	102		5180.001	0.193
	138		5179.977	-4.440
20	102		5179.97	-5.792
	138		5180.02	3.861
30	102		5179.986	-2.703
	138		5180.013	2.510
40	102		5179.997	-0.579
	138		5179.976	-4.633
50	102		5179.978	-4.247
	138		5180.022	4.247

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.