

Test Date	2018/10/27	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	I
Cable Loss	2.92dB	Frequency	TX 5180MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Test Date	2018/10/27	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	I
Cable Loss	2.92dB	Frequency	TX 5200MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Test Date	2018/10/27	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	I
Cable Loss	2.92dB	Frequency	TX 5240MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2A
Cable Loss	3.37dB	Frequency	TX 5260MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			0





Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2A
Cable Loss	3.37dB	Frequency	TX 5300MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2A
Cable Loss	3.37dB	Frequency	TX 5320MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2C
Cable Loss	3.37dB	Frequency	TX 5500MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3






Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2C
Cable Loss	3.37dB	Frequency	TX 5580MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2C
Cable Loss	3.37dB	Frequency	TX 5700MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3










Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5720MHz
Cable Loss	3.37dB	Test Voltage	AC 120V/60HZ (via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3





Test Date	2018/10/31	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	III
Cable Loss	3.91dB	Frequency	TX 5745MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3










Test Date	2018/10/31	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	III
Cable Loss	3.91dB	Frequency	TX 5785MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Test Date	2018/10/31	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	III
Cable Loss	3.97dB	Frequency	TX 5825MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Test Date	2018/10/29	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	I
Cable Loss	2.92dB	Frequency	TX 5190MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/10/29	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	I
Cable Loss	2.92dB	Frequency	TX 5230MHz
Simultaneous Factor 10 log(n) (Note: “n”is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3



