


Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/10/29	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	I
Cable Loss	2.92dB	Frequency	TX 5190MHz
Simultaneous Factor 10 log(n) (Note: “n”is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/10/29	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	I
Cable Loss	2.92dB	Frequency	TX 5230MHz
Simultaneous Factor 10 log(n) (Note: “n”is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2A
Cable Loss	3.37dB	Frequency	TX 5270MHz
Simultaneous Factor 10 log(n) (Note: “n”is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2A
Cable Loss	3.37dB	Frequency	TX 5310MHz
Simultaneous Factor 10 log(n) (Note: “n”is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2C
Cable Loss	3.37dB	Frequency	TX 5510MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2C
Cable Loss	3.37dB	Frequency	TX 5550MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2C
Cable Loss	3.37dB	Frequency	TX 5670MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan






Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/10/31	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2C
Cable Loss	3.37dB	Frequency	TX 5710MHz
Simultaneous Factor 10 log(n) (Note: “n”is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Test Date	2018/10/31	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	III
Cable Loss	3.91dB	Frequency	TX 5755MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3










Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/10/31	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	III
Cable Loss	3.91dB	Frequency	TX 5795MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Test Date	2018/10/29	Temp./Hum.	25°C/55%
Mode	802.11ac-VHT80	UNII Band	I
Cable Loss	2.92dB	Frequency	TX 5210MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3





Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11ac-VHT80	UNII Band	II-2A
Cable Loss	3.37dB	Frequency	TX 5290MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
			3

