



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 8, 2004

RE: LG Electronics

FCC ID: BEJRD5330

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) The radiated ERP testing and transmitter radiated spurious emissions testing appear to be in error. The data tables submitted appear to show a field strength measurement corrected and simply converted to ERP. This is not permitted. Measurements should be made using the substitution method. Kindly explain your procedure in more detail.

William H. Graff
President and Director of Engineering

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.