



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

August 18, 2004

RE: LG Electronics Inc.

FCC ID: BEJRU60PZ61

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Component values on the schematics could not be read. Please provide a higher resolution schematic where the component values are readable.
- 2) The device is capable of many different resolutions and refresh rates. These different resolutions and rates must be investigated to determine worse case (Page 15 of the users manual shows various resolutions possible). Worse case does not always occur at the highest resolution. Was this investigation performed? If not, how can worse case data be assured?
- 3) What was the final resolution/refresh rate for the worse case mode of operation.
- 4) FYI.....I took care of moving the one photograph from the External to Internal Photos for you.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.