







VX1000

Antenna Change

VX1000 R&D Team

Nov 09, 2005

VX1000 Antenna Change

CHANGES	IN DETAIL Please refer to pictures in right side	BEFORE (H/W 1.0)	AFTER (H/W 1.1)
ANTENNA SHAPE	Externally, antenna shape is changed.		
INTERNAL STRUCTURE	The main reason which antenna is changed is extended BOBBIN size in antenna. (Antenna length: 4 mm ↑)		
MATCHING CIRCUIT	Matching circuit is changed like beside pictures.		
EMI COATING	Different coating method	Spray Coating	Evaporation Coating