

## INTERTEK TESTING SERVICE



---

Report No.: 15010067HKG-001

### Equipment Photographs

Model : 5985

(Internal)



## INTERTEK TESTING SERVICE


---

Report No.: 15010067HKG-001

### Equipment Photographs

Model : 5985

(Internal)



## INTERTEK TESTING SERVICE


---

Report No.: 15010067HKG-001

### Equipment Photographs

Model : 5985

(Internal)



**INTERTEK TESTING SERVICE**

Report No.: 15010067HKG-001

## Equipment Photographs

**Model : 5985**

**(Internal)**



FCC ID: BJ4-5985BLE  
IC: 3984A-5985BLE

## INTERTEK TESTING SERVICE


---

Report No.: 15010067HKG-001

### Equipment Photographs

Model : 5985

(Internal)



## INTERTEK TESTING SERVICE

---

Report No.: 15010067HKG-001

### Equipment Photographs

Model : 5985

(Internal)



---

FCC ID: BJ4-5985BLE  
IC: 3984A-5985BLE

## INTERTEK TESTING SERVICE


---

Report No.: 15010067HKG-001

### Equipment Photographs

Model : 5985

(Internal)



## INTERTEK TESTING SERVICE



---

Report No.: 15010067HKG-001

### Equipment Photographs

Model : 5985

(Internal)



---

FCC ID: BJ4-5985BLE  
IC: 3984A-5985BLE

## INTERTEK TESTING SERVICE

---

Report No.: 15010067HKG-001

### Equipment Photographs

Model : 5985

(Internal)

