

	Ant2	5180	NV	-10	-5000	-0.965251	20	PASS
			NV	0	-5000	-0.965251	20	PASS
			NV	10	-5000	-0.965251	20	PASS
			NV	20	-5000	-0.965251	20	PASS
			NV	30	-5000	-0.965251	20	PASS
			NV	40	-6000	-1.158301	20	PASS
			NV	50	-5000	-0.965251	20	PASS
			NV	60	-4000	-0.772201	20	PASS
			NV	70	-4000	-0.772201	20	PASS
	Ant1	5200	NV	-10	-20000	-3.846154	20	PASS
			NV	0	0	0	20	PASS
			NV	10	-20000	-3.846154	20	PASS
			NV	20	0	0	20	PASS
			NV	30	-20000	-3.846154	20	PASS
			NV	40	0	0	20	PASS
			NV	50	-20000	-3.846154	20	PASS
			NV	60	-20000	-3.846154	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5200	NV	-10	-4000	-0.769231	20	PASS
			NV	0	-5000	-0.961538	20	PASS
			NV	10	-5000	-0.961538	20	PASS
			NV	20	-5000	-0.961538	20	PASS
			NV	30	-5000	-0.961538	20	PASS
			NV	40	-6000	-1.153846	20	PASS
			NV	50	-5000	-0.961538	20	PASS
			NV	60	-5000	-0.961538	20	PASS
			NV	70	-5000	-0.961538	20	PASS
	Ant1	5240	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	0	0	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	0	0	20	PASS
			NV	50	0	0	20	PASS
			NV	60	0	0	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5240	NV	-10	-4000	-0.763359	20	PASS
			NV	0	-5000	-0.954198	20	PASS
			NV	10	-6000	-1.145038	20	PASS
			NV	20	-5000	-0.954198	20	PASS
			NV	30	-5000	-0.954198	20	PASS
			NV	40	-6000	-1.145038	20	PASS
			NV	50	-5000	-0.954198	20	PASS
			NV	60	-6000	-1.145038	20	PASS
			NV	70	-6000	-1.145038	20	PASS

	Ant1	5260	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	0	0	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	0	0	20	PASS
			NV	50	0	0	20	PASS
			NV	60	0	0	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5260	NV	-10	-5000	-0.95057	20	PASS
			NV	0	-5000	-0.95057	20	PASS
			NV	10	-5000	-0.95057	20	PASS
			NV	20	-5000	-0.95057	20	PASS
			NV	30	-5000	-0.95057	20	PASS
			NV	40	-5000	-0.95057	20	PASS
			NV	50	-5000	-0.95057	20	PASS
			NV	60	-5000	-0.95057	20	PASS
			NV	70	-6000	-1.140684	20	PASS
	Ant1	5280	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	0	0	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	0	0	20	PASS
			NV	50	0	0	20	PASS
			NV	60	0	0	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5280	NV	-10	-5000	-0.94697	20	PASS
			NV	0	-5000	-0.94697	20	PASS
			NV	10	-5000	-0.94697	20	PASS
			NV	20	-5000	-0.94697	20	PASS
			NV	30	-7000	-1.325758	20	PASS
			NV	40	-5000	-0.94697	20	PASS
			NV	50	-5000	-0.94697	20	PASS
			NV	60	-5000	-0.94697	20	PASS
			NV	70	-5000	-0.94697	20	PASS
	Ant1	5320	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	0	0	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	0	0	20	PASS
			NV	50	0	0	20	PASS
			NV	60	0	0	20	PASS
			NV	70	0	0	20	PASS

	Ant2	5320	NV	-10	-4000	-0.75188	20	PASS
			NV	0	-5000	-0.93985	20	PASS
			NV	10	-5000	-0.93985	20	PASS
			NV	20	-5000	-0.93985	20	PASS
			NV	30	-5000	-0.93985	20	PASS
			NV	40	-5000	-0.93985	20	PASS
			NV	50	-4000	-0.75188	20	PASS
			NV	60	-5000	-0.93985	20	PASS
			NV	70	-5000	-0.93985	20	PASS
	Ant1	5500	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	-20000	-3.636364	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	0	0	20	PASS
			NV	50	0	0	20	PASS
			NV	60	0	0	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5500	NV	-10	-5000	-0.909091	20	PASS
			NV	0	-5000	-0.909091	20	PASS
			NV	10	-4000	-0.727273	20	PASS
			NV	20	-6000	-1.090909	20	PASS
			NV	30	-4000	-0.727273	20	PASS
			NV	40	-6000	-1.090909	20	PASS
			NV	50	-4000	-0.727273	20	PASS
			NV	60	-5000	-0.909091	20	PASS
			NV	70	-5000	-0.909091	20	PASS
	Ant1	5580	NV	-10	0	0	20	PASS
			NV	0	-20000	-3.584229	20	PASS
			NV	10	0	0	20	PASS
			NV	20	-20000	-3.584229	20	PASS
			NV	30	-20000	-3.584229	20	PASS
			NV	40	0	0	20	PASS
			NV	50	0	0	20	PASS
			NV	60	-20000	-3.584229	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5580	NV	-10	-5000	-0.896057	20	PASS
			NV	0	-5000	-0.896057	20	PASS
			NV	10	-6000	-1.075269	20	PASS
			NV	20	-6000	-1.075269	20	PASS
			NV	30	-7000	-1.25448	20	PASS
			NV	40	-6000	-1.075269	20	PASS
			NV	50	-6000	-1.075269	20	PASS
			NV	60	-6000	-1.075269	20	PASS
			NV	70	-5000	-0.896057	20	PASS

	Ant1	5700	NV	-10	0	0	20	PASS
			NV	0	-20000	-3.508772	20	PASS
			NV	10	-20000	-3.508772	20	PASS
			NV	20	-20000	-3.508772	20	PASS
			NV	30	0	0	20	PASS
			NV	40	-20000	-3.508772	20	PASS
			NV	50	-20000	-3.508772	20	PASS
			NV	60	-20000	-3.508772	20	PASS
			NV	70	-20000	-3.508772	20	PASS
	Ant2	5700	NV	-10	-5000	-0.877193	20	PASS
			NV	0	-6000	-1.052632	20	PASS
			NV	10	-5000	-0.877193	20	PASS
			NV	20	-6000	-1.052632	20	PASS
			NV	30	-5000	-0.877193	20	PASS
			NV	40	-6000	-1.052632	20	PASS
			NV	50	-6000	-1.052632	20	PASS
			NV	60	-6000	-1.052632	20	PASS
			NV	70	-6000	-1.052632	20	PASS
	Ant1	5720	NV	-10	-2000	-0.34965	20	PASS
			NV	0	-2000	-0.34965	20	PASS
			NV	10	-2000	-0.34965	20	PASS
			NV	20	-2000	-0.34965	20	PASS
			NV	30	-3000	-0.524476	20	PASS
			NV	40	-3000	-0.524476	20	PASS
			NV	50	-2000	-0.34965	20	PASS
			NV	60	-2000	-0.34965	20	PASS
			NV	70	-3000	-0.524476	20	PASS
	Ant2	5720	NV	-10	-5000	-0.874126	20	PASS
			NV	0	-7000	-1.223776	20	PASS
			NV	10	-6000	-1.048951	20	PASS
			NV	20	-7000	-1.223776	20	PASS
			NV	30	-7000	-1.223776	20	PASS
			NV	40	-6000	-1.048951	20	PASS
			NV	50	-5000	-0.874126	20	PASS
			NV	60	-7000	-1.223776	20	PASS
			NV	70	-6000	-1.048951	20	PASS
	Ant1	5745	NV	-10	0	0	20	PASS
			NV	0	-20000	-3.481288	20	PASS
			NV	10	-20000	-3.481288	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	-20000	-3.481288	20	PASS
			NV	50	0	0	20	PASS
			NV	60	-20000	-3.481288	20	PASS
			NV	70	0	0	20	PASS

	Ant2	5745	NV	-10	-4000	-0.696258	20	PASS
			NV	0	-7000	-1.218451	20	PASS
			NV	10	-4000	-0.696258	20	PASS
			NV	20	-6000	-1.044386	20	PASS
			NV	30	-5000	-0.870322	20	PASS
			NV	40	-7000	-1.218451	20	PASS
			NV	50	-6000	-1.044386	20	PASS
			NV	60	-6000	-1.044386	20	PASS
			NV	70	-6000	-1.044386	20	PASS
	Ant1	5785	NV	-10	-20000	-3.457217	20	PASS
			NV	0	-20000	-3.457217	20	PASS
			NV	10	0	0	20	PASS
			NV	20	-20000	-3.457217	20	PASS
			NV	30	-20000	-3.457217	20	PASS
			NV	40	0	0	20	PASS
			NV	50	-20000	-3.457217	20	PASS
			NV	60	0	0	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5785	NV	-10	-6000	-1.037165	20	PASS
			NV	0	-6000	-1.037165	20	PASS
			NV	10	-6000	-1.037165	20	PASS
			NV	20	-6000	-1.037165	20	PASS
			NV	30	-6000	-1.037165	20	PASS
			NV	40	-6000	-1.037165	20	PASS
			NV	50	-6000	-1.037165	20	PASS
			NV	60	-6000	-1.037165	20	PASS
			NV	70	-6000	-1.037165	20	PASS
	Ant1	5825	NV	-10	-20000	-3.433476	20	PASS
			NV	0	0	0	20	PASS
			NV	10	0	0	20	PASS
			NV	20	-20000	-3.433476	20	PASS
			NV	30	-20000	-3.433476	20	PASS
			NV	40	-20000	-3.433476	20	PASS
			NV	50	-20000	-3.433476	20	PASS
			NV	60	-20000	-3.433476	20	PASS
			NV	70	-20000	-3.433476	20	PASS
	Ant2	5825	NV	-10	-6000	-1.030043	20	PASS
			NV	0	-6000	-1.030043	20	PASS
			NV	10	-5000	-0.858369	20	PASS
			NV	20	-6000	-1.030043	20	PASS
			NV	30	-7000	-1.201717	20	PASS
			NV	40	-5000	-0.858369	20	PASS
			NV	50	-5000	-0.858369	20	PASS
			NV	60	-6000	-1.030043	20	PASS
			NV	70	-6000	-1.030043	20	PASS

11AX40S ISO	Ant1	5190	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	-40000	-7.707129	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	0	0	20	PASS
			NV	50	0	0	20	PASS
			NV	60	0	0	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5190	NV	-10	-5000	-0.963391	20	PASS
			NV	0	-6000	-1.156069	20	PASS
			NV	10	-5000	-0.963391	20	PASS
			NV	20	-5000	-0.963391	20	PASS
			NV	30	-5000	-0.963391	20	PASS
			NV	40	-6000	-1.156069	20	PASS
			NV	50	-6000	-1.156069	20	PASS
			NV	60	-5000	-0.963391	20	PASS
			NV	70	-5000	-0.963391	20	PASS
	Ant1	5230	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	0	0	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	0	0	20	PASS
			NV	50	0	0	20	PASS
			NV	60	0	0	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5230	NV	-10	-5000	-0.956023	20	PASS
			NV	0	-6000	-1.147228	20	PASS
			NV	10	-5000	-0.956023	20	PASS
			NV	20	-5000	-0.956023	20	PASS
			NV	30	-5000	-0.956023	20	PASS
			NV	40	-6000	-1.147228	20	PASS
			NV	50	-6000	-1.147228	20	PASS
			NV	60	-6000	-1.147228	20	PASS
			NV	70	-6000	-1.147228	20	PASS
	Ant1	5270	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	0	0	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	0	0	20	PASS
			NV	50	0	0	20	PASS
			NV	60	0	0	20	PASS
			NV	70	0	0	20	PASS

	Ant2	5270	NV	-10	-4000	-0.759013	20	PASS
			NV	0	-5000	-0.948767	20	PASS
			NV	10	-5000	-0.948767	20	PASS
			NV	20	-7000	-1.328273	20	PASS
			NV	30	-5000	-0.948767	20	PASS
			NV	40	-6000	-1.13852	20	PASS
			NV	50	-5000	-0.948767	20	PASS
			NV	60	-5000	-0.948767	20	PASS
			NV	70	-6000	-1.13852	20	PASS
	Ant1	5310	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	0	0	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	0	0	20	PASS
			NV	50	0	0	20	PASS
			NV	60	0	0	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5310	NV	-10	-6000	-1.129944	20	PASS
			NV	0	-5000	-0.94162	20	PASS
			NV	10	-5000	-0.94162	20	PASS
			NV	20	-5000	-0.94162	20	PASS
			NV	30	-5000	-0.94162	20	PASS
			NV	40	-6000	-1.129944	20	PASS
			NV	50	-6000	-1.129944	20	PASS
			NV	60	-5000	-0.94162	20	PASS
			NV	70	-5000	-0.94162	20	PASS
	Ant1	5510	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	40000	7.259528	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	40000	7.259528	20	PASS
			NV	50	0	0	20	PASS
			NV	60	0	0	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5510	NV	-10	-7000	-1.270417	20	PASS
			NV	0	-6000	-1.088929	20	PASS
			NV	10	-6000	-1.088929	20	PASS
			NV	20	-6000	-1.088929	20	PASS
			NV	30	-6000	-1.088929	20	PASS
			NV	40	-7000	-1.270417	20	PASS
			NV	50	-6000	-1.088929	20	PASS
			NV	60	-6000	-1.088929	20	PASS
			NV	70	-6000	-1.088929	20	PASS

	Ant1	5550	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	0	0	20	PASS
			NV	20	0	0	20	PASS
			NV	30	40000	7.207207	20	PASS
			NV	40	0	0	20	PASS
			NV	50	0	0	20	PASS
			NV	60	40000	7.207207	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5550	NV	-10	-5000	-0.900901	20	PASS
			NV	0	-5000	-0.900901	20	PASS
			NV	10	-5000	-0.900901	20	PASS
			NV	20	-6000	-1.081081	20	PASS
			NV	30	-5000	-0.900901	20	PASS
			NV	40	-5000	-0.900901	20	PASS
			NV	50	-5000	-0.900901	20	PASS
			NV	60	-6000	-1.081081	20	PASS
			NV	70	-7000	-1.261261	20	PASS
	Ant1	5670	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	0	0	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	0	0	20	PASS
			NV	50	0	0	20	PASS
			NV	60	0	0	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5670	NV	-10	-5000	-0.881834	20	PASS
			NV	0	-5000	-0.881834	20	PASS
			NV	10	-5000	-0.881834	20	PASS
			NV	20	-6000	-1.058201	20	PASS
			NV	30	-5000	-0.881834	20	PASS
			NV	40	-6000	-1.058201	20	PASS
			NV	50	-5000	-0.881834	20	PASS
			NV	60	-7000	-1.234568	20	PASS
			NV	70	-5000	-0.881834	20	PASS
	Ant1	5710	NV	-10	-2000	-0.350263	20	PASS
			NV	0	-2000	-0.350263	20	PASS
			NV	10	-3000	-0.525394	20	PASS
			NV	20	-2000	-0.350263	20	PASS
			NV	30	-3000	-0.525394	20	PASS
			NV	40	-2000	-0.350263	20	PASS
			NV	50	-2000	-0.350263	20	PASS
			NV	60	-3000	-0.525394	20	PASS
			NV	70	-3000	-0.525394	20	PASS

	Ant2	5710	NV	-10	-6000	-1.050788	20	PASS
			NV	0	-6000	-1.050788	20	PASS
			NV	10	-6000	-1.050788	20	PASS
			NV	20	-6000	-1.050788	20	PASS
			NV	30	-7000	-1.225919	20	PASS
			NV	40	-7000	-1.225919	20	PASS
			NV	50	-7000	-1.225919	20	PASS
			NV	60	-7000	-1.225919	20	PASS
			NV	70	-7000	-1.225919	20	PASS
	Ant1	5755	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	0	0	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	0	0	20	PASS
			NV	50	-40000	-6.950478	20	PASS
			NV	60	0	0	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5755	NV	-10	-6000	-1.042572	20	PASS
			NV	0	-6000	-1.042572	20	PASS
			NV	10	-5000	-0.86881	20	PASS
			NV	20	-6000	-1.042572	20	PASS
			NV	30	-6000	-1.042572	20	PASS
			NV	40	-6000	-1.042572	20	PASS
			NV	50	-6000	-1.042572	20	PASS
			NV	60	-7000	-1.216334	20	PASS
			NV	70	-6000	-1.042572	20	PASS
	Ant1	5795	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	0	0	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	0	0	20	PASS
			NV	50	0	0	20	PASS
			NV	60	0	0	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5795	NV	-10	-5000	-0.862813	20	PASS
			NV	0	-6000	-1.035375	20	PASS
			NV	10	-5000	-0.862813	20	PASS
			NV	20	-7000	-1.207938	20	PASS
			NV	30	-5000	-0.862813	20	PASS
			NV	40	-5000	-0.862813	20	PASS
			NV	50	-6000	-1.035375	20	PASS
			NV	60	-6000	-1.035375	20	PASS
			NV	70	-6000	-1.035375	20	PASS

11AX80S ISO	Ant1	5210	NV	-10	4000	0.767754	20	PASS
			NV	0	4000	0.767754	20	PASS
			NV	10	4000	0.767754	20	PASS
			NV	20	4000	0.767754	20	PASS
			NV	30	4000	0.767754	20	PASS
			NV	40	4000	0.767754	20	PASS
			NV	50	4000	0.767754	20	PASS
			NV	60	3000	0.575816	20	PASS
			NV	70	3000	0.575816	20	PASS
	Ant2	5210	NV	-10	-5000	-0.959693	20	PASS
			NV	0	-5000	-0.959693	20	PASS
			NV	10	-5000	-0.959693	20	PASS
			NV	20	-5000	-0.959693	20	PASS
			NV	30	-5000	-0.959693	20	PASS
			NV	40	-5000	-0.959693	20	PASS
			NV	50	-5000	-0.959693	20	PASS
			NV	60	-5000	-0.959693	20	PASS
			NV	70	-5000	-0.959693	20	PASS
	Ant1	5290	NV	-10	2000	0.378072	20	PASS
			NV	0	1000	0.189036	20	PASS
			NV	10	1000	0.189036	20	PASS
			NV	20	1000	0.189036	20	PASS
			NV	30	1000	0.189036	20	PASS
			NV	40	2000	0.378072	20	PASS
			NV	50	1000	0.189036	20	PASS
			NV	60	0	0	20	PASS
			NV	70	1000	0.189036	20	PASS
	Ant2	5290	NV	-10	-5000	-0.94518	20	PASS
			NV	0	-5000	-0.94518	20	PASS
			NV	10	-5000	-0.94518	20	PASS
			NV	20	-4000	-0.756144	20	PASS
			NV	30	-5000	-0.94518	20	PASS
			NV	40	-5000	-0.94518	20	PASS
			NV	50	-5000	-0.94518	20	PASS
			NV	60	-5000	-0.94518	20	PASS
			NV	70	-5000	-0.94518	20	PASS
	Ant1	5530	NV	-10	-80000	-14.466546	20	PASS
			NV	0	-80000	-14.466546	20	PASS
			NV	10	-80000	-14.466546	20	PASS
			NV	20	0	0	20	PASS
			NV	30	-80000	-14.466546	20	PASS
			NV	40	0	0	20	PASS
			NV	50	-80000	-14.466546	20	PASS
			NV	60	0	0	20	PASS
			NV	70	-80000	-14.466546	20	PASS

	Ant2	5530	NV	-10	-4000	-0.723327	20	PASS
			NV	0	-5000	-0.904159	20	PASS
			NV	10	-6000	-1.084991	20	PASS
			NV	20	-6000	-1.084991	20	PASS
			NV	30	-5000	-0.904159	20	PASS
			NV	40	-6000	-1.084991	20	PASS
			NV	50	-6000	-1.084991	20	PASS
			NV	60	-5000	-0.904159	20	PASS
			NV	70	-4000	-0.723327	20	PASS
	Ant1	5610	NV	-10	0	0	20	PASS
			NV	0	0	0	20	PASS
			NV	10	0	0	20	PASS
			NV	20	1000	0.178253	20	PASS
			NV	30	1000	0.178253	20	PASS
			NV	40	0	0	20	PASS
			NV	50	1000	0.178253	20	PASS
			NV	60	1000	0.178253	20	PASS
			NV	70	0	0	20	PASS
	Ant2	5610	NV	-10	-5000	-0.891266	20	PASS
			NV	0	-5000	-0.891266	20	PASS
			NV	10	-6000	-1.069519	20	PASS
			NV	20	-6000	-1.069519	20	PASS
			NV	30	-6000	-1.069519	20	PASS
			NV	40	-6000	-1.069519	20	PASS
			NV	50	-5000	-0.891266	20	PASS
			NV	60	-5000	-0.891266	20	PASS
			NV	70	-5000	-0.891266	20	PASS
	Ant1	5690	NV	-10	-3000	-0.527241	20	PASS
			NV	0	-3000	-0.527241	20	PASS
			NV	10	-3000	-0.527241	20	PASS
			NV	20	-3000	-0.527241	20	PASS
			NV	30	-3000	-0.527241	20	PASS
			NV	40	-3000	-0.527241	20	PASS
			NV	50	-2000	-0.351494	20	PASS
			NV	60	-2000	-0.351494	20	PASS
			NV	70	-2000	-0.351494	20	PASS
	Ant2	5690	NV	-10	-6000	-1.054482	20	PASS
			NV	0	-7000	-1.230228	20	PASS
			NV	10	-7000	-1.230228	20	PASS
			NV	20	-7000	-1.230228	20	PASS
			NV	30	-6000	-1.054482	20	PASS
			NV	40	-6000	-1.054482	20	PASS
			NV	50	-7000	-1.230228	20	PASS
			NV	60	-6000	-1.054482	20	PASS
			NV	70	-7000	-1.230228	20	PASS

	Ant1	5775	NV	-10	-60000	-10.38961	20	PASS
			NV	0	0	0	20	PASS
			NV	10	-60000	-10.38961	20	PASS
			NV	20	0	0	20	PASS
			NV	30	0	0	20	PASS
			NV	40	-60000	-10.38961	20	PASS
			NV	50	0	0	20	PASS
			NV	60	0	0	20	PASS
			NV	70	-60000	-10.38961	20	PASS
	Ant2	5775	NV	-10	-5000	-0.865801	20	PASS
			NV	0	-5000	-0.865801	20	PASS
			NV	10	-5000	-0.865801	20	PASS
			NV	20	-6000	-1.038961	20	PASS
			NV	30	-6000	-1.038961	20	PASS
			NV	40	-5000	-0.865801	20	PASS
			NV	50	-5000	-0.865801	20	PASS
			NV	60	-5000	-0.865801	20	PASS
			NV	70	-5000	-0.865801	20	PASS