




Label materials

Surface material : PET WH50 (polyethylene terephthalate)

Bonding material : Adhesive (PA-T1)