


SRD-Testreport

CETECOM ICT Services GmbH Saarbruecken, Germany

Test report No.: 4-1748-01-02/05

Date: 2005-10-04

Page 66 of 76



SRD-Testreport

CETECOM ICT Services GmbH Saarbruecken, Germany

Test report No.: 4-1748-01-02/05

Date: 2005-10-04

Page 67 of 76




SRD-Testreport

CETECOM ICT Services GmbH Saarbruecken, Germany

Test report No.: 4-1748-01-02/05

Date: 2005-10-04

Page 68 of 76




SRD-Testreport

CETECOM ICT Services GmbH Saarbruecken, Germany

Test report No.: 4-1748-01-02/05

Date: 2005-10-04

Page 69 of 76




SRD-Testreport

CETECOM ICT Services GmbH Saarbruecken, Germany

Test report No.: 4-1748-01-02/05

Date: 2005-10-04

Page 70 of 76




CETECOM ICT Services GmbH Saarbruecken, Germany

Test report No.: 4-1748-01-02/05

Date: 2005-10-04

Page 71 of 76




SRD-Testreport

CETECOM ICT Services GmbH Saarbruecken, Germany

Test report No.: 4-1748-01-02/05

Date: 2005-10-04

Page 72 of 76




SRD-Testreport

CETECOM ICT Services GmbH Saarbruecken, Germany

Test report No.: 4-1748-01-02/05

Date: 2005-10-04

Page 73 of 76




SRD-Testreport

CETECOM ICT Services GmbH Saarbruecken, Germany

Test report No.: 4-1748-01-02/05

Date: 2005-10-04

Page 74 of 76




CETECOM ICT Services GmbH Saarbruecken, Germany

Test report No.: 4-1748-01-02/05

Date: 2005-10-04

Page 75 of 76



SRD-Testreport

CETECOM ICT Services GmbH Saarbruecken, Germany

Test report No.: 4-1748-01-02/05

Date: 2005-10-04

Page 76 of 76

