





(Photo 1)

FCC ID: BR8TD-521




(Photo 2)

FCC ID: BR8TD-521




(Photo 3)

FCC ID: BR8TD-521



(Photo 4)

FCC ID: BR8TD-521




(Photo 5)

FCC ID: BR8TD-521



(Photo 6)

FCC ID: BR8TD-521




(Photo 7)

FCC ID: BR8TD-521



(Photo 8)

FCC ID: BR8TD-521




(Photo 9)

FCC ID: BR8TD-521




(Photo 10)

FCC ID: BR8TD-521




(Photo 11)

FCC ID: BR8TD-521




(Photo 12)

FCC ID: BR8TD-521




(Photo 13)

FCC ID: BR8TD-521



(Photo 14)

FCC ID: BR8TD-521




(Photo 15)

FCC ID: BR8TD-521



(Photo 16)


FCC ID: BR8TD-521



(Photo 17)

FCC ID: BR8TD-521





(Photo 19)

FCC ID: BR8TD-521