


6.5 Radiated Measurement Photos

Mode: Tx



Mode: Charging



8.6 Photos of Conduction Measuring Setup

Mode : Charging

