

Response to E05-000003-1

- 1 & 2. A revised manual has been uploaded.
3. New internal photos have been uploaded
4. New external photos have been uploaded
5. The test report has been revised with corrected cal dates.
6. The readings are average readings, not peak.
7. The cal dates for the HP-8449B are correct on page 42
8. The 15.237 test conditions have been revised in the test report to reflect 15.31(e) testing.