


INTERTEK TESTING SERVICE

Report No.: 17062161HKG-002

Equipment Photographs

Model: MHA50

(Internal)



FCC ID: BWY-MHA50

IC: 2483A-MHA50



INTERTEK TESTING SERVICE

Report No.: 17062161HKG-002

Equipment Photographs

Model: MHA50

(Internal)



FCC ID: BWY-MHA50

IC: 2483A-MHA50



INTERTEK TESTING SERVICE

Report No.: 17062161HKG-002

Equipment Photographs

Model: MHA50

(Internal)



FCC ID: BWY-MHA50

IC: 2483A-MHA50



INTERTEK TESTING SERVICE

Report No.: 17062161HKG-002

Equipment Photographs

Model: MHA50

(Internal)





INTERTEK TESTING SERVICE

Report No.: 17062161HKG-002

Equipment Photographs

Model: MHA50

(Internal)





INTERTEK TESTING SERVICE

Report No.: 17062161HKG-002

Equipment Photographs

Model: MHA50

(Internal)





INTERTEK TESTING SERVICE

Report No.: 17062161HKG-002

Equipment Photographs

Model: MHA50

(Internal)



FCC ID: BWY-MHA50

IC: 2483A-MHA50



INTERTEK TESTING SERVICE

Report No.: 17062161HKG-002

Equipment Photographs

Model: MHA50

(Internal)




INTERTEK TESTING SERVICE

Report No.: 17062161HKG-002

Equipment Photographs

Model: MHA50

(Internal)



INTERTEK TESTING SERVICE

Report No.: 17062161HKG-002

Equipment Photographs

Model: MHA50

(Internal)

