



228 Ambassador Drive
Mississauga ON
Canada
L5T 2J2

April 16, 2014

Edna Prado
Office of Engineering and Technology

Re: FCC ID BZ5DTR10SC
Correspondence Reference number 45621

With regards to the missing installation and operations manual for this product, please find attached our publication: "PUB14-01_Frontier DTR10SCG2 Installation_Rev0.pdf" detailing the installation and first turn-on procedure. This product is intended for operation by personnel with minimal technical abilities, and therefore its operation is intended to be as plug-and-play as possible.

Also, in regards to the internal photographs, I have included a more comprehensive photograph with details illustrated. I apologize; the previous photograph detailed only the power amplifier portion of the product. Should you require additional pictures please let me know.

If there is anything else you need please do not hesitate to contact me.

Sincerely,

A handwritten signature in black ink, which appears to read "John Tremblay". The signature is fluid and cursive, with the first and last names being clearly legible.

John Tremblay
V. P. Engineering



LARCAN

U.S. Tel: 1-303-665-8000 Fax: 1-303-673-9900 **Canada** Tel: 1-905-564-9222 Fax: 1-905-564-9244
www.larcan.com Email: sales@larcan.com