

Reason for Change:

Changing the PCB from 4 layers to double sides.

Effect on Change:

No effect.
