





Internal PIFA PCB antenna. Disabled by Firmware at factory



Flexible Stainless Steel



Omni EV5C Hardware (not for sale)

SN.OMEV5C-0059 FW Ver. 4.3.9.P1.29.P0

Lead - Free Yes

Marvell Silicon 8388 A2 / 803D B1B

MAC address 00-0D-3A-7A-DE-5D



MLU4020-D68(LF)

1156H000079

F08

OK
MADE IN
TAIWAN
12

Microsoft

9504B

