

From: Annie_Chang@adt.com.tw [mailto:Annie_Chang@adt.com.tw]
Sent: Tuesday, April 25, 2006 1:57 AM
To: steve.cheng
Subject: Re : TCB Review Comments for (C06-0424a- C3K1074- Microsoft keyboard)

Dear Steve:

I had upload the modified user's manual to server.
Please find it. Thank you.

Best Regards,

Annie Chang (張嘉宴)
LinKou Documentation & Certification Dept. of ADT Corp.
web site: www.adt.com.tw
E-mail: annie_chang@adt.com.tw
tel: 886-2-26052180 Ext. 1176
fax: 886-2-26051924

"steve.cheng" <steve.cheng@nacsemc.com>

2006/04/25 上午 01:18

收件人 Annie_Chang@adt.com.tw

副本抄送 Jessica_Cheng@adt.com.tw

送

主旨 TCB Review Comments for (C06-0424a- C3K1074- Microsoft keyboard)

TCB Review Comments for (C06-0424a- C3K1074- Microsoft keyboard)

-EMC-

Question #1: Per FCC Section 15.105 Information to the user, following info is required to the user in manual or related document. Please supply.

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.

- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Best regards,

Steve Cheng
Curtis-Straus LLC