

APPENDIX A – SAMPLE LABEL

Labeling Requirements

The sample label shown shall be *permanently affixed* at a conspicuous location on the device and be readily visible to the user at the time of purchase.

DAEWOO  MICROWAVE OVEN (HOUSEHOLD) MODEL NO.: KOT-1J0U8 POWER INPUT 120V 60Hz AC ONLY, 1.5KW, SINGLE PHASE WITH GROUNDING. OUTPUT FREQUENCY 2450MHz FCC ID: C5F7NF1JMO950N MADE IN CHINA DHHS CODE: H7NF DISTRIBUTED BY: DAEWOO ELECTRONICS AMERICA, INC. 7769 NW 48TH STREET, SUITE 375, DORAL, FL 33166, U.S.A. SERIAL NO.: MANUFACTURED:		CAUTION *THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY. WARNING *DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF ENCLOSURE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH-VOLTAGE POTENTIALS. *TO ENSURE CONTINUED PROTECTION AGAINST SHOCK HAZARD CONNECT TO PROPERLY GROUNDED OUTLETS ONLY. *CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRIC SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL-DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: FAN MOTOR, LOW VOLTAGE TRANSFORMER (TOUCH CONTROL TYPE), TIMER & TIMER MOUNTING BRACKET (MECHANICAL TYPE). RISK OF ELECTRIC SHOCK. NON REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES, DO NOT REMOVE FASTENERS N-001 *NOT FOR BUILT-IN INSTALLATION
VIKING RANGE LLC VMOH330SS UL/CSA RATING: 120 / 120 VAC 1.5 / 1.5 KW 60Hz OUTPUT: 950 / 950 W 2450MHz MICROWAVE OVEN FOUR MICRO-ONDES TEST LOAD: 275CC WATER FOR HOUSEHOLD USE ONLY NOT FOR COMMERCIAL USE POUR USAGE DOMESTIQUE SEULEMENT NON DESTINE A UN USAGE COMMERCIAL COMPLIES WITH DHHS RADIATION PERFORMANCE STANDARDS 21 CFR SUBCHAPTER J SINGLE PHASE GENERATOR: MAGNETRON 4.1k Vp VIKING RANGE LLC, 111 Front Street Greenwood, MS 38930 MADE IN China SERIAL NO. MANUFACTURED:		

● FCC ID Location of EUT

