




0.036 CHAMFER		
ADDITIONAL SIGNS ON THE PART		
REVISION NOTE# 20. C3: ADDED Ø.047	FB	
DEPTH OF HOLE TO THRU HOLE		
M. A4: .286 WAS .300		



4

3