

Appendix 3: Photographs of test setup

Except Transmitter Timeout

Below 960 MHz



Above 960 MHz



UL Japan, Inc.
Yokowa EMC Lab.

108 Yokowa-cho, Ise-shi, Mie-ken, 516-1106 JAPAN

Telephone: +81 596 39 1485

Facsimile: +81 596 39 0232

13-EM-F0429

FCC ID : CKENJJ-200
Test report No. : 10042776Y-B-R1

Issued date : January 28, 2014

Transmitter Timeout



End of Report

UL Japan, Inc.
Yokowa EMC Lab.

108 Yokowa-cho, Ise-shi, Mie-ken, 516-1106 JAPAN

Telephone: +81 596 39 1485

Facsimile: +81 596 39 0232

13-EM-F0429