






8-12-C
32

If the vehicle does
not move properly,
replace the batteries
with new ones. (R5)

© NIKKO
MADE IN CHINA
U.S. PAT. 4,888,888

FCC ID : CVTRD3210H

Grantee Name: NIKKO Co., Ltd.

This device complies with Part 15 of the FCC Rules.
Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and
(2) This device must accept any interference received,
including interference that may cause undesired
operation.



10001

ITEM NO.
RDC-20531



