

PARTS LIST/TUNE UP INFORMATION

Parts List:

The only active RF transistor in the amplifier is Motorola's MHW916.

Tune Up Information

There are no adjustments needed to tune this amplifier. Alignment test procedure is to simply test for -65 dBc conducted harmonic compliance and stability.