



Date: 10/4/2023

Subject : Request to change in Identification.

Dear FCC / TCB,

This Change of Identification request applies for a new FCC ID: as established in 47CFR 2.933(b) for a currently approved device. This application by Physio-Control, Inc. (now a part of Stryker) will establish a new FCC ID: CZO23LPCR2 under Physio-Control, Inc. grantee code. The original grant held by Quectel Wireless Solutions Co.,Ltd., will remain in effect.

Per 2.933(b)

1. The original identification is XMR201906EG21G
2. The original grant date is 06/07/2019.
3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.

The following files are submitted with this application:

- Cover Letter
- External Photos
- FCC ID label format and location

Sincerely,

A handwritten signature in black ink, appearing to read "Timothy Rand".

Timothy Rand
Sr Compliance Standards Engineer
Physio-Control, Inc. (now a part of Stryker)
11811 Willows Rd NE
Redmond WA 98052
+1 425 867 4477
tim.rand@stryker.com
www.physio-control.com

Emergency Care

11811 Willows Road NE, Redmond, WA 98052 USA | P +1 425 867 4000 | Toll-free +1 800 442 1142 | stryker.com