



Date: 10/4/2023

Subject : Request to change in Identification.

Dear FCC / TCB,

This Change of Identification request applies for a new FCC ID: as established in 47CFR 2.933(b) for a currently approved device. This application by Physio-Control, Inc. (now a part of Stryker) will establish a new FCC ID: CZO23LPCR2T under Physio-Control, Inc. grantee code. The original grant held by Telit Communications S.p.A. will remain in effect.

Per 2.933(b)

1. The original identification is RI7WE310F5
2. The original grant date is 01/25/2021.
3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.

The following files are submitted with this application:

- Cover Letter
- External Photos
- FCC ID label format and location

Sincerely,

A handwritten signature in black ink that reads "Timothy Rand".

Timothy Rand
Sr Compliance Standards Engineer
Physio-Control, Inc. (now a part of Stryker)
11811 Willows Rd NE
Redmond WA 98052
+1 425 867 4477
tim.rand@stryker.com
www.physio-control.com

Emergency Care

11811 Willows Road NE, Redmond, WA 98052 USA | P +1 425 867 4000 | Toll-free +1 800 442 1142 | stryker.com