DBSM/DBSMD Transmitter

Labeling and Marking

A1B1 - US version

DBSM





Label location - actual size

DBSMD





Label locations - actual size

15 October 2020 - BAH generated file, using SMWB/SMDWB file as base.
19 October 2020 - BAH edited file to remove FCC ID on the E01.
29 October 2020 - BAH resized art; parts are not common with SMWB/SMDWB.
30 October 2020 - BAH reconfgured E01 upper badge to take better advantage of spacing.
12 November 2020 - BAH reconfigured DBSMD to reflect as engraved (Wes/Bob/Steve produced as shown).
See “Approvals” file for notes regarding this change.
22 January 2021 BAH split the US and E01 drawings into two separate documents, per Paul via request from Lab

Please circulate for approval and return to Bridget

Bridget _____

Karl _____

Gordon _____

Bob _____

Wes _____

John T. _____

Lectrosonics, Inc.
Rio Rancho, NM USA
T (505) 892.4501
F (505) 892-6243
Contact engineer: John Tscherne - john.tscherne@lectrosonics.com
Contact artwork: Bridget Harrington - bridget.harrington@lectrosonics.com