



Port A


Channel 953.250MHz




Channel 955.850MHz



Channel 956.850MHz




Channel 959.450MHz




Test Site	WZ-SR5	Test Engineer	Lynn Yang
Test Date	2024-10-29	Test Mode	Mode 8

Port A


Channel 941.900MHz



Channel 946.750 MHz




Channel 951.600 MHz




Port A


Channel 953.250MHz




Channel 955.850MHz



Channel 956.850MHz




Channel 959.450MHz




Port B


Channel 941.900MHz



Channel 946.750 MHz




Channel 951.600 MHz




Port B


Channel 953.250MHz




Channel 955.850MHz



Channel 956.850MHz




Channel 959.450MHz




Port C


Channel 941.900MHz



Channel 946.750 MHz




Channel 951.600 MHz




Port C


Channel 953.250MHz




Channel 955.850MHz



Channel 956.850MHz




Channel 959.450MHz




Port D


Channel 941.900MHz



Channel 946.750 MHz




Channel 951.600 MHz




Port D


Channel 953.250MHz




Channel 955.850MHz



Channel 956.850MHz



Channel 959.450MHz



Test Site	WZ-SR5	Test Engineer	Lynn Yang
Test Date	2024-10-01 2024-10-09	Test Mode	Mode 9

Port A


Channel 941.900MHz



Channel 946.750 MHz




Channel 951.600 MHz




Port A


Channel 953.250MHz




Channel 955.850MHz



Channel 956.850MHz




Channel 959.450MHz




Port B


Channel 941.900MHz



Channel 946.750 MHz




Channel 951.600 MHz




Port B


Channel 953.250MHz



Channel 955.850MHz



Channel 956.850MHz



Channel 959.450MHz

