



Intertek Testing Services

ETL SEMKO

Report No.: 0004949

Tested By: Ben, Report No.: 0004949

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0004949

Tested By: Ben, Report No.: 0004949

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start Stop Step IF BW Detector M-Time Atten Preamp OpRge

450k 30M 5k 10k PK 20ms AUTO LN OFF 60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

0.61500	14.4	48.0
---------	------	------

0.76500	16.5	48.0
---------	------	------

1.10500	6.5	48.0
---------	-----	------

4.02500	31.8	48.0
---------	------	------

* limit exceeded

Ctrl No.: N/A