

.....

14085 Howard Rd
Dayton, MD 21036

TRP/Cetecom bvba

July 28, 2001

FCC Laboratory
7435 Oakland Mills Rd
Dayton, MD 21036

Re: FCC ID:DMO-SK5012, EA101844

FCC Examiner,

During the application filing process for FCCID:DMOSK5012, EA101843, the internet connection failed. As a result I was unable to complete the filing and submission of the fee payment form. I have requested that FCCID:DMOSK5012, EA101843, be dismissed or otherwise deleted. I have refiled the equipment under the above FCCID with a hyphen in the identifier which allowed the completion of the filing and fee payment process. After dismissal or deletion of the application under EA101843, please correct the FCC ID listed on the Form 731 to read FCCID:DMOSK5012. This will correct the FCCID on the Form 731 to correspond with the FCC ID label submitted in this application.

Sincerely,

Phillip Inglis
Consultant

.....