


	360 Herndon Parkway, Suite 1400	Report number	2002057
	Herndon, VA 20170	FCC	Part 15.247
	http://www.rheintech.com	Industry Canada	RSS-210
		FCC ID	E2X-SWL2200P
		M/N	SWL-2200P

APPENDIX N: ANTENNA PHOTOGRAPHS




PHOTOGRAPH 5: FRONT VIEW OF ANTENNA

	360 Herndon Parkway, Suite 1400	Report number	2002057
	Herndon, VA 20170	FCC	Part 15.247
	http://www.rheintech.com	Industry Canada	RSS-210
		FCC ID	E2X-SWL2200P
		M/N	SWL-2200P




PHOTOGRAPH 6: BACK VIEW OF PCB ANTENNA

	360 Herndon Parkway, Suite 1400	Report number	2002057
	Herndon, VA 20170	FCC	Part 15.247
	http://www.rheintech.com	Industry Canada	RSS-210
		FCC ID	E2X-SWL2200P
		M/N	SWL-2200P




PHOTOGRAPH 7: PCB OF PATCH ANTENNA

	360 Herndon Parkway, Suite 1400	Report number	2002057
	Herndon, VA 20170	FCC	Part 15.247
	http://www.rheintech.com	Industry Canada	RSS-210
		FCC ID	E2X-SWL2200P
		M/N	SWL-2200P




PHOTOGRAPH 8: FRONT PCB OF ANTENNA

	360 Herndon Parkway, Suite 1400	Report number	2002057
	Herndon, VA 20170	FCC	Part 15.247
	http://www.rheintech.com	Industry Canada	RSS-210
		FCC ID	E2X-SWL2200P
		M/N	SWL-2200P



PHOTOGRAPH 9: BACK PCB OF ANTENNA

	360 Herndon Parkway, Suite 1400	Report number	2002057
	Herndon, VA 20170	FCC	Part 15.247
	http://www.rheintech.com	Industry Canada	RSS-210
		FCC ID	E2X-SWL2200P
		M/N	SWL-2200P



PHOTOGRAPH 10:


SWL2200P_PCI CARD WITH 2200M

	360 Herndon Parkway, Suite 1400	Report number	2002057
	Herndon, VA 20170	FCC	Part 15.247
	http://www.rheintech.com	Industry Canada	RSS-210
		FCC ID	E2X-SWL2200P
		M/N	SWL-2200P




PHOTOGRAPH 11: BACK OF SWL2200P

	360 Herndon Parkway, Suite 1400	Report number	2002057
	Herndon, VA 20170	FCC	Part 15.247
	http://www.rheintech.com	Industry Canada	RSS-210
		FCC ID	E2X-SWL2200P
		M/N	SWL-2200P




PHOTOGRAPH 12: FRONT OF PCI CARD WITHOUT MINI PCI WLAN RADIO

	360 Herndon Parkway, Suite 1400	Report number	2002057
	Herndon, VA 20170	FCC	Part 15.247
	http://www.rheintech.com	Industry Canada	RSS-210
		FCC ID	E2X-SWL2200P
		M/N	SWL-2200P




PHOTOGRAPH 13: FRONT VIEW OF 2200M

	360 Herndon Parkway, Suite 1400	Report number	2002057
	Herndon, VA 20170	FCC	Part 15.247
	http://www.rheintech.com	Industry Canada	RSS-210
		FCC ID	E2X-SWL2200P
		M/N	SWL-2200P



PHOTOGRAPH 14: BACK VIEW OF 2200M

	360 Herndon Parkway, Suite 1400	Report number	2002057
	Herndon, VA 20170	FCC	Part 15.247
	http://www.rheintech.com	Industry Canada	RSS-210
		FCC ID	E2X-SWL2200P
		M/N	SWL-2200P



PHOTOGRAPH 15: FRONT VIEW OF 2200M WITHOUT SHIELD