

October 5, 2006

Letter of correction

Product : Amplifier (13.56MHz RFID System)
Applicant : OMRON Corporation
Model : V680-HA63
FCC ID : E4E6CYSIDV6800306

Report number “27AE0026-YK” had an error in the FCC ID number referenced “E4E6CYCIDV6800306”. Please note that this letter corrects the FCC ID number in the report to FCC ID: E4E6CYSIDV6800306.

Sincerely,

Toyokazu Imamura
Testing Engineer
Yamakita EMC Lab.
EMC Service Dept.
UL Apex Co., Ltd.