

Report No.: 9810707


Tested By: Hong, Report No.: 9810707

Scan Settings (1 Range)

Frequencies				Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Final Measurement: X QF
 Meas Time: 1 s
 Subranges: 16
 Acc Margin: 20dB



PAGE 1

Ctrl. No.: N/A

FCC ID: EHK615T

Report No.: 9810707

Tested By: Hong, Report No.: 9810707

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
16.62000	44.9	48.0

* limit exceeded

Ctrl. No.: N/A

FCC ID: BHK615T