


**EMC Technologies Report Number: M050508\_Cert\_WLL4070\_11abg\_DTS\_BT**

**APPENDIX K1**  
**Harmonics - Atheros 802.11a**



**Harmonics – Channel 149**

Marker 1 [T1] RBW 100 kHz RF Att 30 dB  
Ref Lvl -1.92 dBm VBW 300 kHz  
15 dBm 5.68937876 GHz SWT 9.8 s Unit dBm




Date: 8.JUN.2005 16:31:01



**Harmonics - Channel 157**

Marker 1 [T1] REW 100 kHz RF Att 30 dB  
Ref Lvl -1.23 dBm VBW 300 kHz  
15 dBm 5.76753507 GHz SWT 9.8 s Unit dBm




Date: 8.JUN.2005 16:24:51



**Harmonics - Channel 165**

Marker 1 [T1] RBW 100 kHz RF Att 30 dB  
Ref Lvl -0.64 dBm VBW 300 kHz  
15 dBm 5.76753507 GHz SWT 9.8 s Unit dBm




Date: 8.JUN.2005 16:11:50



**Harmonics - Channel 152 (Turbo)**

Marker 1 [T1] RBW 100 kHz RF Att 30 dB  
Ref Lvl -1.56 dBm VBW 300 kHz  
15 dBm 5.68937876 GHz SWT 9.8 s Unit dBm




Date: 8.JUN.2005 16:35:48



**Harmonics - Channel 160 (Turbo)**

Marker 1 [T1] RBW 100 kHz RF Att 30 dB  
Ref Lvl -1.42 dBm VBW 300 kHz  
15 dBm 5.76753507 GHz SWT 9.8 s Unit dBm



Date: 8.JUN.2005 16:39:33

