


EMC Technologies Report Number: M050508_Cert_WLL4070_11abg_NII_BT

APPENDIX K
Harmonics - WLL4070 802.11a (NII)




Harmonics – Channel 36

Date: 9.JUN.2005 10:46:52



Harmonics - Channel 42

Marker 1 [T1] RBW 300 kHz RF Att 30 dB
Ref Lvl 0.07 dBm VBW 1 MHz
15 dBm 5.22044088 GHz SWT 1.1 s Unit dBm




Date: 9.JUN.2005 10:50:54



Harmonics - Channel 50

Marker 1 [T1] RBW 300 kHz RF Att 30 dB
Ref Lvl 0.35 dBm VBW 1 MHz
15 dBm 5.22044088 GHz SWT 1.1 s Unit dBm




Date: 9.JUN.2005 10:54:04



Harmonics - Channel 52

Marker 1 [T1] RBW 300 kHz RF Att 30 dB
Ref Lvl 6.02 dBm VBW 1 MHz
15 dBm 5.22044088 GHz SWT 1.1 s Unit dBm




Date: 9.JUN.2005 10:38:31



Harmonics - Channel 58

Marker 1 [T1] RBW 300 kHz RF Att 30 dB
Ref Lvl 4.26 dBm VBW 1 MHz
15 dBm 5.22044088 GHz SWT 1.1 s Unit dBm




Date: 9.JUN.2005 10:56:22



Harmonics - Channel 64

Marker 1 [T1]	RBW	300 kHz	RF Att	30 dB
Ref Lvl	5.66 dBm	VBW	1 MHz	
15 dBm	5.29859719 GHz	SWT	1.1 s	Unit dBm



Date: 9.JUN.2005 10:43:02

