

From: hliana@ccsemc.com.tw  
Sent: Friday, January 16, 2004 12:38 AM  
To: scheng@ccsemc.com  
Cc: cert@ccsemc.com.tw  
Subject: Re: AN04T3593 NUTEK ALARM ELVNTRCA

Hi Steve,

Please find the attached email by Naomi below.

If you have any further comments, please feel free to contact us.

Best regards,

Liana Hsiung (&#29066;&#36899;&#26525;)  
=====

&#31243;&#26234;&#31185;&#25216;&#32929;&#20221;&#26377;&#38480;&#20844;&#21496;  
Compliance Certification Services Inc. (Hsintien Lab.)  
No.165, Chunghsen Road, Hsintien City, Taipei Hsien, Taiwan  
TEL:+886-2-2217-0894\*10  
FAX:+886-2-2217-1029  
hliana@ccsemc.com.tw  
=====

----- &#36681;&#21576;&#32773; hliana/ccsemc &#26044; 2004/01/16 04:20 PM -----  
znaomi  
&#24373;&#23478;&#33729;  
2004/01/16 03:11 PM

&#25910;&#20214;&#20154;&#65306; hliana/ccsemc@ccsemc  
&#21103;&#26412;&#25220;&#36865;&#65306;  
&#20027;&#26088;&#65306; Re: AN04T3593 NUTEK ALARM  
ELVNTRCA&#36899;&#32080;

TCB Review Questions for AN04T3593 NUTEK ALARM ELVNTRCA

Question #1: Schematics is not readable please resubmit a clear copy.  
--->Attached please find Schematics.jpg.

Question #2: Test report page 10, 15.205 is marked as not necessary. Please explain why 15.205 do not apply?  
--->Sorry about that! Attached please find C30710402-RP (NUTEK ELVNTRCA)new.pdf.

Question #3: Does all 4 buttons generate the same code sequence? If not, why same duty-cycle correct-factor was used in the emission measurement? Please explain.  
--->Sorry about that! Attached please find C30710402-RP (NUTEK ELVNTRCA)new.pdf.

Question #4: Test report page 5, indicated following items are all out of cal. Please explain why they were used in the test.  
R&S MEASURE RECEIVER / ADVANTEST SPECTRUM ANALYZER / SCHAFFNER ANTENNA

BELDEN CABLE / SCHAFFNER PRE-AMPLIFIER / CCS Site NSA

--->The date tested in July 07, 2003 and July 10, 2003. so those equipment aren't out of cal. or maybe u have any suggestion in the question.

Although u didnt ask the Question #5 #6 in this e-mail, but u ask the question in the "AN04T3592 NUTEK ALARM ELVNTRCB" e-mail, so i update it here.

Question #5: Users manual does not have the info according to "CFR47 Section 15.21". Please revise users manual to include the info.

--->Attached please find new users manual.

Question #6: Users manual is very blurry; please resubmit a clear copy if possible.

--->Sorry about that! because the customer didnt provide us the file, just paper only. if there is any question, please don't hesitate to contact me.

Best Regards

Naomi Zhang

TCB Review Questions for AN04T3593 NUTEK ALARM ELVNTRCA

-EMC-

Question #1: Schematics is not readable please resubmit a clear copy.

Question #2: Test report page 10, 15.205 is marked as not necessary. Please explain why 15.205 do not apply?

Question #3: Does all 4 buttons generate the same code sequence? If not, why same duty-cycle correct-factor was used in the emission measurement? Please explain.

Question #4: Test report page 5, indicated following items are all out of cal. Please explain why they were used in the test.

R&S MEASURE RECEIVER  
ADVANTEST SPECTRUM ANALYZER  
SCHAFFNER ANTENNA  
BELDEN CABLE  
SCHAFFNER PRE-AMPLIFIER  
CCS Site NSA

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best Regards

Steve Cheng / TCB Technical Reviewer  
Compliance Certification Services  
561F Monterey Road  
Morgan Hill, CA 95037  
Tel:(408) 463-0885 x: 119  
Fax:(408) 463-0888  
scheng@ccsemc.com  
<http://www.ccsemc.com>