



Intertek Testing Services

ETL SEMKO

Report No.: 0308136
Weather Band

Tested By: Hong, Report No.: 0308136


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement: x QP / + AV

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



FCC ID: E154

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0308136
Weather Band

Tested By: Hong, Report No.: 0308136

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

no Results

Frequency	AV Level	AV Limit
MHz	dBuV	dBuV

16.20500	35.5	50.0
----------	------	------

* limit

FCC ID: EMOT154

Ctrl No.: N/A