

Response to E04-000028

1. A revised tune-up statement has been uploaded.
2. MPE Calculations have been uploaded.
3. This issue has been resolved by the FCC.
4. A FAA letter has been uploaded.