




APPENDIX B. Internal Photographs of EUT







580502



SPORTON International Inc.

TEL : 886-2-2696-2468


FAX : 886-2-2696-2255

FCC ID : ESN-SP70B

PAGE NUMBER : B3 OF B14


ISSUED DATE : Sep. 27, 2005

Rev. 01





580502



SPORTON International Inc.

TEL : 886-2-2696-2468


FAX : 886-2-2696-2255

FCC ID : ESN-SP70B


PAGE NUMBER : B5 OF B14


ISSUED DATE : Sep. 27, 2005


Rev. 01



580502







SPORTON International Inc.

TEL : 886-2-2696-2468


FAX : 886-2-2696-2255

FCC ID : ESN-SP70B

PAGE NUMBER : B9 OF B14

ISSUED DATE : Sep. 27, 2005

Rev. 01



SPORTON International Inc.

TEL : 886-2-2696-2468


FAX : 886-2-2696-2255

FCC ID : ESN-SP70B

PAGE NUMBER : B10 OF B14

ISSUED DATE : Sep. 27, 2005

Rev. 01



SPORTON International Inc.

TEL : 886-2-2696-2468


FAX : 886-2-2696-2255

FCC ID : ESN-SP70B

PAGE NUMBER : B11 OF B14

ISSUED DATE : Sep. 27, 2005

Rev. 01



580502

SPORTON International Inc.

TEL : 886-2-2696-2468


FAX : 886-2-2696-2255

FCC ID : ESN-SP70B

PAGE NUMBER : B12 OF B14

ISSUED DATE : Sep. 27, 2005

Rev. 01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC ID : ESN-SP70B

PAGE NUMBER : B13 OF B14

ISSUED DATE : Sep. 27, 2005

Rev. 01



580502

