




INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 15110840HKG-001
FCC ID: EW780-0048-00
IC: 1135B-80004800

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 15110840HKG-001
FCC ID: EW780-0048-00
IC: 1135B-80004800



INTERTEK TESTING SERVICES

Internal photos





Test Report Number: 15110840HKG-001
FCC ID: EW780-0048-00
IC: 1135B-80004800

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



Test Report Number: 15110840HKG-001
FCC ID: EW780-0048-00
IC: 1135B-80004800

INTERTEK TESTING SERVICES

Internal photos

