

INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

Equipment Photographs

Model : VM345 BU

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

Equipment Photographs

Model : VM345 BU

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

Equipment Photographs

Model : VM345 BU

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

Equipment Photographs


Model : VM345 BU

(Internal)



Report No.: 16060975HKG-001

© 2006 The Authors
Journal compilation © 2006 Blackwell Publishing Ltd



FCC ID: EW780-0289-00
IC: 1135B-80028900



INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

Equipment Photographs

Model : VM345 BU

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

Equipment Photographs

Model : VM345 BU

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

Equipment Photographs

Model : VM345 BU

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

Equipment Photographs

Model : VM345 BU

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

Equipment Photographs

Model : VM345 BU

(Internal)

