




INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 18081094HKG-001, 18081094HKG-002
FCC ID: EW780-0348-00
IC: 1135B-80135800

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 18081094HKG-001, 18081094HKG-002
FCC ID: EW780-0348-00
IC: 1135B-80135800



INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos

