




INTERTEK TESTING SERVICES

Internal photos





Internal photos





INTERTEK TESTING SERVICES

Internal photos




INTERTEK TESTING SERVICES

Internal photos




INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 16040719HKG-001
FCC ID: EW780-0381-00
IC: 1135B-80038100

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 16040719HKG-001
FCC ID: EW780-0381-00
IC: 1135B-80038100



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 16040719HKG-001
FCC ID: EW780-0381-00
IC: 1135B-80038100



INTERTEK TESTING SERVICES

Internal photos




INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 16040719HKG-001
FCC ID: EW780-0381-00
IC: 1135B-80038100



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos

