



INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 16070865HKG-001
FCC ID: EW780-0443-00
IC: 1135B-80044300

INTERTEK TESTING SERVICES


Internal photos



Test Report Number: 16070865HKG-001
FCC ID: EW780-0443-00
IC: 1135B-80044300

INTERTEK TESTING SERVICES


Internal photos



Test Report Number: 16070865HKG-001
FCC ID: EW780-0443-00
IC: 1135B-80044300

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 16070865HKG-001
FCC ID: EW780-0443-00
IC: 1135B-80044300

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 16070865HKG-001
FCC ID: EW780-0443-00
IC: 1135B-80044300

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 16070865HKG-001
FCC ID: EW780-0443-00
IC: 1135B-80044300

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 16070865HKG-001
FCC ID: EW780-0443-00
IC: 1135B-80044300

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 16070865HKG-001
FCC ID: EW780-0443-00
IC: 1135B-80044300

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 16070865HKG-001
FCC ID: EW780-0443-00
IC: 1135B-80044300

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 16070865HKG-001
FCC ID: EW780-0443-00
IC: 1135B-80044300

INTERTEK TESTING SERVICES


Internal photos



Test Report Number: 16070865HKG-001
FCC ID: EW780-0443-00
IC: 1135B-80044300

INTERTEK TESTING SERVICES


Internal photos



Test Report Number: 16070865HKG-001
FCC ID: EW780-0443-00
IC: 1135B-80044300

INTERTEK TESTING SERVICES

Internal photos



Test Report Number: 16070865HKG-001
FCC ID: EW780-0443-00
IC: 1135B-80044300