



vtech
www.vtechbabycare.com
VTech Customer Service 1-800-595-9511
FCC ID: EW780-2365-00B
IC: 1135B-80236500B
HVIN: 35-201931BUA
LISTED
UL62368-1
CSA C22.2 No.62368-1
A0073
Model: VM819 BU
SN:XXXXXXXXXXX
MANUFACTURED IN CHINA
vtech
www.vtechbabycare.com
VTech Customer Service 1-800-595-9511
FCC ID: EW780-2365-00B
IC: 1135B-80236500B
HVIN: 35-201931BUA
LISTED
UL62368-1
CSA C22.2 No.62368-1
A0073
Model: VM819-2 BU
SN:XXXXXXXXXXX
MANUFACTURED IN CHINA
vtech
www.vtechbabycare.com
VTech Customer Service 1-800-595-9511
FCC ID: EW780-2365-00B
IC: 1135B-80236500B
HVIN: 35-201931BUA
LISTED
UL62368-1
CSA C22.2 No.62368-1
A0073
Model: 819 Max BU
MYVT2 SN:XXXXXXXXXXX
MANUFACTURED IN MALAYSIA
vtech
www.vtechbabycare.com
VTech Customer Service 1-800-595-9511
FCC ID: EW780-2365-00B
IC: 1135B-80236500B
HVIN: 35-201931BUA
LISTED
UL62368-1
CSA C22.2 No.62368-1
A0073
Model: 819 Max Twin BU
MYVT2 SN:XXXXXXXXXXX
MANUFACTURED IN MALAYSIA

BU


6V 400mA


vtech
www.vtechbabycare.com
VTech Customer Service 1-800-595-9511
FCC ID: EW780-2365-00B
IC: 1135B-80236500B
HVIN: 35-201931BUA
LISTED
UL62368-1
CSA C22.2 No.62368-1
A0073
Model: VM819 BU
SN:XXXXXXXXXXX
MANUFACTURED IN CHINA