

INTERTEK TESTING SERVICES


Internal photos

Internal photo – Base unit





INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 16062056HKG-001, 16062056HKG-002
FCC ID: EW780-9783-00
IC: 1135B-80978300


INTERTEK TESTING SERVICES

Internal photos




INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES


Internal photos



Test Report Number: 16062056HKG-001, 16062056HKG-002
FCC ID: EW780-9783-00
IC: 1135B-80978300


INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos




INTERTEK TESTING SERVICES

Internal photos




INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



Internal photo – Mic




INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos

