




INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos




INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



Test Report Number: 19010133HKG-001, 19010133HKG-003
FCC ID: EW780-9870-00
IC: 1135B-80169800

INTERTEK TESTING SERVICES

Internal photos

