PHOTOS - TEST SETUP

Company: Itron

Product Name: ERG-5600-501

Report No.: ITRO67 – Test Setup Photos

1. Test Setup Photographs

1.1.1. Test Setup



Digital Emissions ERG-5600-501, 1-18GHz, Front

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com

Spurious Emissions ERG-5600-501, 1-18GHz, Back



Spurious Emissions ERG-5600-501, 1-18GHz, Front

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com



Digital Emissions ERG-5600-1, 30MHz-1GHz, Front



Digital Emissions ERG-5600-501, 30MHz-1GHz, Back

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com



ERG-5600-501, 30MHz-1GHz, Back



ERG-5600-501, 30MHz-1GHz, Front

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com

1.1.2. Test Setup - RF#2 - Conducted



RF Conducted Test Setup 1



RF Conducted Test Setup 2

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com

ERG-5600-501 was deemed by Itron to be the worst case and covers the following models also. Please see Declaration of Similarity in reports:

ERG-5600-502
ERG-5600-503
ERG-5600-505
ERG-7600-501
ERG-7600-502
ERG-7600-503
ERG-7600-505
ERW-1350-002
ERW-1650-002
ERW-1650-010

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com

575 Boulder Court
Pleasanton, California 94566, USA
Tel: +1 (925) 462 0304
Fax: +1 (925) 462 0306
www.micomlabs.com