PHOTOS - TEST SETUP

Company: Itron

Product Name: ERW-1350-001

Report No.: ITRO67 – Test Setup Photos

1. Test Setup Photographs

1.1.1. Test Setup



Digital Emissions ERW-1350-001 External Antenna, 1-18GHz, Front

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com



Digital Emissions ERW-1350-001, 1-18GHz, Back



Digital Emissions ERW-1350-001, 1-18GHz, Front

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com



Digital Emissions ERW-1350-001, 30MHz-1GHz, Front



Digital Emissions ERW-1350-001, External Antenna, 1-18GHz, Back

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com



ERW-1350-001, 30MHz-1GHz, Front

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com



Spurious Emissions ERW-1350-001, 1-18GHz, Back



Spurious Emissions ERW-1350-001, External Antenna, 1-18GHz, Back

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com

Spurious Emissions ERW-1350-001, External Antenna, 1-18GHz, Front



Spurious Emissions EWR-1350-001, 1-18GHz, Front

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com



Digital Emissions ERW-1350-001 External Antenna, 30MHz-1GHz, Back

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com



Digital Emissions ERW-1350-001 External Antenna, 30MHz-1GHz, Front



Digital Emissions ERW-1350-001, 30MHz-1GHz, Back

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com

ERW-1350-001 External Antenna, 30MHz-1GHz, Back



ERW-1350-001 External Antenna, 30MHz-1GHz, Front

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com



ERW-1350-001, 30MHz-1GHz, Back

1.1.2. Test Setup - RF#2 - Conducted



RF Conducted Test Setup 1

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com



RF Conducted Test Setup 2

ERW-1350-001 was deemed by Itron to be the worst case and covers the following models also. Please see Declaration of Similarity in reports:

ERW-1650-001
ERW-1650-005
ERW-1650-008
ERW-1650-009
ERG-7600-515

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.
MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com

575 Boulder Court
Pleasanton, California 94566, USA
Tel: +1 (925) 462 0304
Fax: +1 (925) 462 0306
www.micomlabs.com